

**December 3, 2013** 

TO:

All Interested Quoters

SUBJECT:

ADDENDUM #3- RFQ #14-0481GE - Coquina Boat Ramp Dock

Repairs

This information is issued to modify, and/or clarify the request for quotation document.

**Q 1.** For the replacement of the headers, will there be one or two bolts per piling? Currently there are 2 bolts per piling but adding two more bolt holes may weaken the piling more than adding 1 bolt hole. The 5' wide sections should structurally accommodate the single bolt but the 2x12 R/S on the wide section would definitely need 2 per pile.

**A 1.** Yes, 1 bolt per piling for the 5' section headers – we agree that the 2x12 needs 2 bolts. If the condition of the piling is such that 2 new holes will weaken it, we'll replace the piling and that will be covered under the time & material contingency portion of the RFQ.

The RFQ submittal deadline date and time remains unchanged.

George Earnest CPPB

December 3, 2013

Purchasing, Buyer

Date