

BID TABULATION

ITQ 19-R070937SR- FIRE LINE BACKFLOW PREVENTER SERVICES

Accurate Backflow Testing, Inc.

Access Fire
Protection, Inc.

Cintas Corporation

Item

Size (Inches)

Unit Price

Unit Price

Unit Price

INSPECTION/CERTIFICATION TESTING PRICE

1	¾" by-pass	\$25.00	\$38.00	\$55.00
2	1"	\$25.00	\$39.00	\$45.00
3	1.5"	\$30.00	\$39.00	\$45.00
4	2"	\$50.00	\$39.00	\$45.00
5	2.5"	\$10.00	\$40.00	\$45.00
6	3"	\$85.00	\$40.00	\$45.00
7	4"	\$125.00	\$50.00	\$55.00
8	6"	\$125.00	\$65.00	\$55.00
9	8"	\$125.00	\$85.00	\$55.00
10	10"	\$125.00	\$100.00	\$55.00
11	12"	\$0.00	\$120.00	\$55.00
12	14"	\$0.00	\$140.00	\$55.00
13	16"	\$0.00	\$160.00	\$55.00

REPAIR PRICING FOR RPZ PREVENTERS - REPLACEMENT OF A RUBBER REPAIR KIT FOR THE FOLLOWING

14	¾" by-pass	\$165.00	\$120.00	\$271.00
15	1"	\$165.00	\$125.00	\$289.00
16	1.5"	\$285.00	\$150.00	\$305.00
17	2"	\$285.00	\$200.00	\$305.00
18	2.5"	\$1,175.00	\$250.00	\$469.00
19	3"	\$1,175.00	\$330.00	\$469.00
20	4"	\$1,175.00	\$430.00	\$514.00
21	6"	\$1,375.00	\$450.00	\$1,071.00
22	8"	\$1,375.00	\$660.00	\$1,328.00
23	10"	\$1,575.00	\$750.00	\$1,369.00
24	12"	\$0.00	\$900.00	\$1,309.00
25	14"	\$0.00	\$1,000.00	N/A
26	16"	\$0.00	\$1,100.00	N/A

REPAIR PRICING FOR DCV PREVENTERS

27	¾" by-pass	\$165.00	\$90.00	\$243.00
28	1"	\$165.00	\$95.00	\$243.00
29	1.5"	\$225.00	\$120.00	\$268.00
30	2"	\$225.00	\$200.00	\$268.00
31	2.5"	\$1,075.00	\$250.00	\$349.00
32	3"	\$1,075.00	\$250.00	\$349.00
33	4"	\$1,075.00	\$300.00	\$368.00
34	6"	\$1,175.00	\$380.00	\$925.00
35	8"	\$1,175.00	\$460.00	\$1,151.00
36	10"	\$1,375.00	\$525.00	\$1,191.00
37	12"	\$1,375.00	\$600.00	\$1,254.00
38	14"	\$0.00	N/A	N/A
39	16"	\$0.00	N/A	N/A

REPLACEMENT PRICING FOR RPZ PREVENTERS

40	¾" by-pass	\$475.00	\$375.00	\$541.25
----	------------	----------	----------	----------

BID TABULATION

ITQ 19-R070937SR- FIRE LINE BACKFLOW PREVENTER SERVICES

		Accurate Backflow Testing, Inc.	Access Fire Protection, Inc.	Cintas Corporation
41	1"	\$985.00	\$500.00	\$483.75
42	1.5"	\$1,275.00	\$800.00	\$753.75
43	2"	\$1,375.00	\$1,000.00	\$923.75
44	2.5"	\$3,147.00	\$2,800.00	\$2,685.00
45	3"	\$3,363.00	\$3,200.00	\$4,063.75
46	4"	\$4,112.00	\$4,000.00	\$3,687.50
47	6"	\$6,632.00	\$5,000.00	\$5,676.25
48	8"	\$16,287.00	\$8,000.00	\$9,448.75
49	10"	\$19,440.00	\$10,000.00	\$14,108.75
50	12"	\$0.00	\$12,000.00	\$21,047.50
51	14"	\$0.00	\$0.00	\$0.00
52	16"	\$0.00	\$0.00	\$0.00
<u>REPLACEMENT PRICING FOR DCV PREVENTERS</u>				
53	¾" by-pass	\$395.00	\$375.00	\$341.25
54	1"	\$925.00	\$450.00	\$355.00
55	1.5"	\$1,145.00	\$700.00	\$706.25
56	2"	\$1,255.00	\$900.00	\$752.50
57	2.5"	\$2,847.00	\$2,500.00	\$2,320.00
58	3"	\$3,125.00	\$3,000.00	\$2,426.25
59	4"	\$3,712.00	\$3,600.00	\$3,215.00
60	6"	\$5,732.00	\$4,400.00	\$3,671.25
61	8"	\$14,287.00	\$6,600.00	\$8,415.00
62	10"	\$18,440.00	\$8,900.00	\$12,810.00
63	12"	\$0.00	\$11,500.00	\$19,067.50
64	14"	\$0.00	\$0.00	\$0.00
65	16"	\$0.00	\$0.00	\$0.00
<u>REPLACEMENT OF DETECTOR CHECK ASSEMBLIES</u>				
66	¾" by-pass	\$165.00	\$745.00	\$800.00
67	1"	\$924.00	\$800.00	\$1,000.00
68	1.5"	\$1,145.00	\$850.00	\$1,200.00
<u>OS & Y REPACKING</u>				
69	3"	\$155.00	\$140.00	\$343.75
70	4"	\$155.00	\$150.00	\$343.75
71	6"	\$155.00	\$150.00	\$543.75
72	8"	\$155.00	\$150.00	\$543.75
73	10"	\$205.00	\$175.00	\$563.75
74	12"	\$235.00	\$175.00	\$563.75
75	14"	\$0.00	\$200.00	\$0.00
76	16"	\$0.00	\$200.00	\$0.00
<u>OS & Y REPLACEMENT</u>				
77	3"	\$952.00	\$625.00	\$885.00
78	4"	\$1,147.00	\$675.00	\$1,742.50
79	6"	\$1,545.00	\$975.00	\$2,062.50
80	8"	\$2,519.00	\$1,125.00	\$2,715.00
81	10"	\$4,515.00	\$1,625.00	\$4,320.00
82	12"	\$6,155.00	\$2,000.00	\$5,155.00

BID TABULATION				
ITQ 19-R070937SR- FIRE LINE BACKFLOW PREVENTER SERVICES				
		Accurate Backflow Testing, Inc.	Access Fire Protection, Inc.	Cintas Corporation
83	14"	\$0.00	\$2,400.00	\$0.00
84	16"	\$0.00	\$2,800.00	\$0.00
REPAIR & REPLACEMENT SERVICES				
85	Hourly labor rate for regular hours	\$85.00	\$70.00	\$110.00
86	Hourly labor rate for overtime hours	\$127.50	\$105.00	\$165.00
87	Percentage markup over Contractor's cost for parts, materials & equipment	45.00%	15.00%	10.00%