

November 25, 2013

TO: All Interested Quoters

SUBJECT: ADDENDUM #2- RFQ #14-0481GE - Coquina Boat Ramp Dock

Repairs

This information is issued to modify, and/or clarify the request for quotation document.

2.5 CCA is required for all wood components except for the decking.

The support structure under the decking of the widest section of the docks (the approximately 12' X 20' section at the corner of both docks) shall have new 2" X 12" rough-sawn boards installed at each header. There shall be one of these boards double-bolted on each side of the existing header location. This work shall be added to the lump sum pricing for the North and South docks; Quote Price Form items 1 through 4.

The RFQ submittal deadline date and time remains unchanged.

George Karnest CPPB

Purchasing, Buyer

November 25, 2012

Date