MANATEE COUNTY GOVERNMENT

INTENT TO AWARD

SUBJECT	Repair of the docks at the Coquina Boat Ramp	DATE POSTED	SE 12/18/13 V
PURCHASING REPRESENTATIVE	George Earnest CPPB, PH (941) 749-3044	DATE CONTRACT SHALL BE AWARDED	
DEPARTMENT	Natural Resources	CONSEQUENCES IF DEFERRED	Hazardous conditions for the public, close down the ramp.
SOLICITATION	RFQ 14-0481GE, Coquina Boat Ramp Dock Repairs	AUTHORIZED BY DATE	Dennis Wallace
	ACTIC	ON DESIRED	1
Authorization to award	the contract to Sunshine Dock	& Seawall, Inc.	
Federal/State law(s), administrative ruling(s), N	ULATING AUTHORITY Ianatee County Comp Pla resolutions, policy.)	n/Land Development Code,
Manatee Code of Laws	3		
	BACKGRO	UND/DISCUSSION	
	18, 2013 RFQ 14-0481GE fo vere issued. On December 6,		ck Repairs was posted. Three received.
	ation of the quote response owest quote is recommended		all, Inc. as the responsive and
SUMMARY	Recommend awarding th	e contract to Sunshine Do	ock & Seawall, Inc.
АТТАСНМ	ENTS	COS	т
Quote Price Tab	oulation Sheet	\$40,897	7.00

1

QUOTE PRICE TABULATION SHEET

DESCRIPTION			LUM	IP SUM PRICE
Northern Dock using galvanized hardware			\$ 8,468.00	
Northern Dock using stainless steel hardware			\$ 10,818.00	
Southern Dock using galvanized hardware			\$ 8,968.00	
Southern Dock using	thern Dock using stainless steel hardware			
Contingency Labor Rate	\$ 25.00	X 40	HOURS =	\$ 1,000
Contingency Percent markup materials	% 15 X		\$100 =	\$ 115.00
	Northern Dock using Southern Dock using Southern Dock using Contingency Labor Rate Contingency Percent markup	Northern Dock using stainless steeSouthern Dock using galvanizedSouthern Dock using stainless steeContingency Labor Rate\$ 25.00Contingency Percent markup materials% 15	Northern Dock using stainless steel hardwareSouthern Dock using galvanized hardwareSouthern Dock using stainless steel hardwareContingency Labor Rate\$ 25.00X 40Contingency Percent markup materials% 15X	Northern Dock using stainless steel hardware\$ 10,818.00Southern Dock using galvanized hardware\$ 8,968.00Southern Dock using stainless steel hardware\$ 11,628.00Contingency Labor Rate\$ 25.00X 40 HOURS =Contingency Percent markup materials% 15X \$100 =

RFQ #14-0481GE for Coquina Boat Ramp Dock Repairs

		RAM Marin	e Services, Ir	nc.	
ITEM	DESCRIPTION			LUMP	SUM PRICE
1	Northern Dock using galvanized hardware			\$ 12,000.00	
2	Northern Dock using stainless steel hardware			\$ 13,100.00	
3	Southern Dock using galvanized hardware			\$ 12,765.00	
4	Southern Dock using	Southern Dock using stainless steel hardware			
5	Contingency Labor Rate	\$ 55.00	X 40 HOURS =		\$ 2,200
6	Contingency Percent markup materials	% 10	x	\$100 =	\$ 110.00
	TOTAL QUOTE PRIC	E	\$ 54,040.00		

ITEM	DESCRIPTION			LUM	P SUM PRICE	
1	Northern Dock using galvanized hardware			\$ 19,591.79		
2	Northern Dock using stainless steel hardware			\$ 20,204.27		
3	Southern Dock using galvanized hardware			\$ 20,555.79		
4	Southern Dock using stainless steel hardware			\$ 21,168.27		
5	Contingency Labor Rate	\$ 35.00	X 40 HOURS =		HOURS =	\$ 1,4000
6	Contingency Percent markup materials	% 10	o x		\$100 =	\$ 110.00
	TOTAL QUOTE PRIC	E	\$ 83,030.1	2		

	Dun	can Seawall,	Dock & Boat	Lift, LLC	
ITEM	DESCRIPTION			LUMF	SUM PRICE
1	Northern Dock using galvanized hardware			\$ 19,981.00	
2	Northern Dock using stainless steel hardware			\$ 21,355.00	
3	Southern Dock using galvanized hardware			\$ 20,698.00	
4	Southern Dock using stainless steel hardware			\$ 21,948.00	
5	Contingency Labor Rate	\$ 63.00	X 40	HOURS =	\$ 2,520
6	Contingency Percent markup materials	% 15	×	\$100 =	\$ 115.00
	TOTAL QUOTE PRIC	E	\$ 86,617.00		

Marine Contracting Group, Inc.						
ITEM	DES	CRIPTION	LUMI	P SUM PRICE		
1	Northern Dock using galvanized hardware			\$ 23,749.00		
2	Northern Dock using stainless steel hardware			\$ 25,379.00		
3	Southern Dock using galvanized hardware \$21,749.00					
4	Southern Dock using	g stainless ste	el hardware	\$ 23,379.00		
5	Contingency Labor Rate	\$ 60.00	X 40	HOURS =	\$ 2,400	
6	Contingency Percent markup materials	% 15	x	\$100 =	\$ 115.00	
	TOTAL QUOTE PRIC	E	\$ 96,771.00			

TEM	DESCRIPTION			LUM	P SUM PRICE
1	Northern Dock using galvanized hardware			\$ 27,840.00	
2	Northern Dock using stainless steel hardware			\$ 28,840.00	
3	Southern Dock using galvanized hardware			\$ 29,140.00	
4	Southern Dock using stainless steel hardware			\$ 30,140.00	
5	Contingency Labor Rate	\$ 45.00	X 40 HOURS		\$ 1,800
6	Contingency Percent markup materials	% 0	X \$100 =		\$ 100.00