



Financial Management Department
Purchasing Division
1112 Manatee Ave W Suite 803
Bradenton, FL 34205
Phone: (941) 749-3074
www.mymanatee.org

Email

August 24, 2015

TO: All Interested Bidders

SUBJECT: Invitation for Bid #15-1947DC
51st Street West Gravity Sewer Replacement ADDENDUM #4

Bidders are hereby notified that this Addendum shall be acknowledged on the Bid Form and made a part of the above named bidding and contract documents.

1. Provide manufacturer for the SDR 26 PVC gasketed saddle.
Response: IPEX USA LLC,
http://www.nacopvc.com/Files/site/2015_Catalog_PDF/Section10.pdf
2. Specification Section 02623 Polyvinyl Chloride (PVC) Pipe (Gravity Sewer) - the attached specification is added for saddle connections.
3. **Question:** Include Record Drawings in the Total Construction Sub-Total Costs".

Response: Record Drawings shall remain as stated in Addendum #2 Bid Form Item 19, Record Drawings.

4. **Question:** Reference Addendum #3, Item 4, does this response take precedence over the milling and overlay depth shown in Detail UG-12 on plan sheet 21 of 24?

Response: Yes, the area indicated for Milling and Resurfacing shall be to a depth of 1-inch.

If you have submitted a bid prior to receiving this addendum you may request in writing that your original, sealed bid be returned to your firm. All sealed bids received will be opened on the date stated.

Bids will be received at Manatee County Purchasing, 1112 Manatee Avenue West, Suite 803, Bradenton, Florida 34205 until **September 1, 2015 at 3:00 P.M.**

Sincerely,


Melissa M. Wendel, CPPO
Purchasing Official

/dcr
Attachment

SECTION 02623 POLYVINYL CHLORIDE (PVC) PIPE (GRAVITY SEWER)

3.15 A. **SADDLE CONNECTIONS**

1. **General:** All saddle connections into existing sewer mains shall be made with a wye or tee saddle, as directed by the plans or County.
2. **Scoring and Tapping:** The sewer main to be saddled shall be scored to the approximate shape of wye or tee and shall be cut with a hole cutter. The tap holes shall be cleanly machined and may be further worked by hand to provide a true and neat opening for the collar wye or tee saddle. Pipe damaged during this operation shall be repaired or replaced. The County representative shall be the sole judge as to the method of repair or replacement.
3. **Securement:** The collar wye or tee shall be secured to the sewer main with a catalytic epoxy resin. The saddle shall be secured to the main with stainless steel straps of sufficient strength that no movement will occur during the setting of the epoxy resin.
4. **Cleaning:** The saddling operation shall be carried out in a workmanlike manner. Chips, dirt, and epoxy resin shall be kept out of the sewer main being saddled. If directed by the County, the reach of sewer main saddled shall be flushed and cleaned using a hydrocleaner or vacuum truck.