

1112 Manatee Avenue West Bradenton, FL 34205 purchasing@mymanatee.org

Solicitation Addendum

Addendum No.:
Solicitation No.:
Solicitation Title:
Addendum Date:
Procurement Contact:

1 ITQ No. 23-R082199JH Manhole and Sewer Main Repair August 11, 2023 Jeb Hayter, Procurement Agent III

ITQ No. 23-R082199JH is amended as set forth herein. Responses to questions posed by prospective bidders are provided below. This Addendum is hereby incorporated in and made a part of ITQ No. 23-R082199JH.

The deadline to submit all inquiries concerning interpretation, clarification or additional information pertaining to this ITQ was August 8, 2023, at 3:00 P.M. ET.

REPLACE:

ATTACHMENT G, QUOTE FORM

Replace Attachment G, Quote form with the Attachment G, Quote Form Revised issued with this Addendum 1, hereby incorporated into this ITQ.

QUESTIONS AND RESPONSES:

- Q1. Can you confirm that 4104 Plumosa Terrace Bradenton, FL 34210 is the correct address for the non-mandatory site visit?
- R1. Yes, that is the correct address for the non-mandatory site visit.
- Q2. What is the width and depth of the manhole?
- R2. 48" wide and 96" deep.
- Q3. Do you want us to include the cost of any leak repairs in with the lump sum quote or would you prefer a separate leak injection repair quote by linear foot?
- R3. This is the replacement of the manhole with a new polymer, there should not be any leaks to repair.

- Q4. Would traffic cones be sufficient for traffic control, or do we need to include additional manpower and traffic control device measures in our quote?
- R4. All traffic control would need to follow the proper Florida Department of Transportation (FDOT) Maintenance of Traffic (MOT) Index sheet and any MOT plan would need to be submitted to the County for review before the start of any work.
- Q5. Is the County going to notify the residents prior to the proposed work, especially the homeowner at 4104 Plumosa Terrace?
- R5. The homeowner at 4104 Plumosa Terrace has been informed of the intent to make repairs to the manhole. It shall be the responsibility of the awarded contractor to communicate with the homeowner once work begins so the homeowner will know who to communicate with should any issues arise during construction.
- Q6. Is the contractor responsible for the removal and replacement of the decorative gravel in the R/W? if so, please advise where to apply this task in the bid tab.
- R6. Yes, the contractor is responsible for all restorative work to the property. Preconstruction pictures are recommended to document the before and after appearance. See revised Attachment G, Quote Form below.

Q7. Is the contractor responsible for any geotechnical testing or record drawing?

R7. Yes, the Contractor is responsible for both.

Q8. Is there any as-built information and elevations for the existing sewer?

R8. No, the County does not have as-builts for this sewer.

NOTE:

Deleted items will be struck through, added or modified items will be <u>underlined</u>. All other terms and conditions remain as stated in the ITQ.

INSTRUCTIONS:

Receipt of this Addendum must be acknowledged as instructed in the solicitation document. Failure to acknowledge receipt of this Addendum may result in the response being deemed non-responsive.

END OF ADDENDUM

AUTHORIZED FOR RELEASE

ATTACHMENT G, QUOTE FORM - (REVISED)

ITQ NO. 23-R082199JH

MANHOLE AND SEWER MAIN REPAIR

Bidders must provide prices for each line item for their bid to be considered responsive.

ITEM	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL
1	Mobilization and Demobilization	1	LS		
2	Site Restoration				
3	Decorative Landscaping Curbing	30	LF		
<u>4</u>	Additional Decorative Landscaping	<u>1</u>	LS		
5	MANHOLE				
6	Install Concrete Manhole, 4' dia	8	VF		
7	PIPE (GRAVITY SEWER)				
8	PVC, SDR 26, 8" (SEWER) 10' each direction	20	LF		
9	MISCELLANEOUS				
10	By-pass Pumping System	1	LS		
11	Temp. Structures, by-pass purposes	2	EA		
12	Erosion Control	1	LS		
13	Traffic Control	1	LS		
				BID SUBTOTAL	
CONTINGENCY - USED ONLY WITH COUNTY APPROVAL				10%	
				BID TOTAL	
				WITH	
				CONTINGENCY	

To be considered responsive, it is the sole responsibility of the bidder to correctly calculate and manually enter all sub-total, contingency, and total bid prices

Bidder Name_____

Authorized Signature_____